

INSTRUCTIONS FOR PROPER MAINTENANCE OF MOTOR BRUSHES

For all presses and dryers with DC Motors: Motor brushes must be replaced after approximately every 2,000 hours of operation. Failure to perform this required maintenance could damage the motor and motor control board.

For MOTORS, CIRCUIT BOARDS and more

CALL TOLL-FREE: 800.444.PART



A Division of The A.W.T. World Trade Group
4321 N. Knox Ave., Chicago IL 60641 USA
773.725.4900 • Fax: 773.777.0909

REPLACEMENT PARTS AND REMANUFACTURING SERVICES FOR SCREEN PRINTING EQUIPMENT
parts@gpiparts.com • www.gpiparts.com